

Pavement Coring Report

Project Name: East 347th Street Resurfacing
Project Number: 232528 **Prime Contractor:** ----
Project Owner: City of Eastlake **Paving Contractor:** ----
Location: East 347th **Core Diameter:** 4"
Date: 03/08/24 **Type:** Thickness ___ Exploratory X
Technician: Scott Pirc

Core #	Location	Cored Material Description	Actual Material Thickness In Inches	Plan Depth	Condition/Type of Subgrade -Aggregate Size -Remarks	
1	Hse. #1183 E. 347th St. 8'6" from back of curb. See attached map.	Concrete	7.5	N/A	2" max aggregate - limestone	
		Sub-total cored	7.5		Base material is gravel w some clay.	
2	Hse. #1124 E. 347th St. 7' from back of curb. See attached map.	Concrete	7.5	N/A	2" max aggregate - limestone	
		Sub-total cored	7.5		Base material is clay.	
		Total Cored	15.0			

Pavement Coring Report

Project Name: East 347th Street Resurfacing

Project Number: 232528

Project Owner: City of Eastlake

Location: East 347th

Date: 03/08/24

Prime Contractor: ----

Paving Contractor: ----

Core Diameter: 4"

Type: Thickness ___ Exploratory X

Technician: Scott Pirc

CORE #1



CORE LOCATION



CORE OPENING



CORE SAMPLE



BASE MATERIAL

Pavement Coring Report

Project Name: East 347th Street Resurfacing

Project Number: 232528

Project Owner: City of Eastlake

Location: East 347th

Date: 03/08/24

Prime Contractor: ----

Paving Contractor: ----

Core Diameter: 4"

Type: Thickness ___ Exploratory X

Technician: Scott Pirc

CORE #2



CORE LOCATION



CORE OPENING



CORE SAMPLE



BASE MATERIAL

Eastlawn Dr

Stevens Blvd

Core #1

Core #2

E 347th St

E 347th St

