## DOCUMENT 003126 - EXISTING HAZARDOUS MATERIAL INFORMATION

## 1.1 EXISTING HAZARDOUS MATERIAL INFORMATION

- A. This Document with its referenced attachments is part of the Procurement and Contracting Requirements for Project. They provide Owner's information for Bidders' convenience and are intended to supplement rather than serve in lieu of Bidders' own investigations. They are made available for Bidders' convenience and information, but are not a warranty of existing conditions. This Document and its attachments are not part of the Contract Documents.
- B. An existing asbestos report for Project, prepared by Terracon Consulting, Inc., dated May 13, 2019, is available for viewing as appended to this Document.
- C. Related Requirements:
  - 1. Document 003132 "Geotechnical Data" for reports and soil-boring data from geotechnical investigations that are made available to bidders.
  - 2. Section 024119 "Selective Structure Demolition" for requirements involving removal of materials suspected of containing hazardous materials.

## END OF DOCUMENT 003126